

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2490)

Set ¼ sec. post, from which
A B.Oak 4" dia., bears S.35°W., 35 lks. dist.
A Fir 15" dia., bears N.35°W., 98 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Dec. 1965 - C.S. File 52/125-21

Found - 1" I.P., S.35°E., 1.8 ft. of actual corner and location.
Orig. 15" now 40" Fir, N.35°W., 64.7 ft. and 66.5 ft. to I.P. mentioned above. Open and shows "/T" scribe on partially burned faces.

No trace of SW. BT.
DID NOT SET BRASS CAP because of log lying over corner point.
New BTs- 24" D.Fir N.32°W., 26.5 ft. mkd. ¼ S30 CS BT.
20" D.Fir S.52°E., 7.0 ft. mkd. ¼ S31 CS BT.
Bearings and distances from iron pipe.
Corner lies on moderate NE. slope approx. 450 ft. West of road.

Survey by Donald Bentz PLS #839 - For: International Paper Co. March 1983 - M 90-38 A&B

Set 1" x 36" Iron pipe in concrete with brass cap mkd. T23S R7W PLS 839 1/4 30 31 1982, from which new BTs:
26" Fir bears N.26°E., 49.4 ft. mkd. ¼ S30 BT.
14" Fir bears S.9°E., 35.0 ft. mkd. ¼ S31 BT.
1" I.Pipe bears S.35°E., 1.8 ft.