

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2489)

-----  
Set post cor. to secs. 29, 30, 31 and 32, from which  
A Maple 36" dia., bears S.15°E., 274 lks. dist.  
An Ash 8" dia., bears S.12½°W., 236 lks. dist.  
A Willow 6" dia., bears N.87¼°W., 297 lks. dist.  
No tree in sec. 29 convenient to mark, drove charred post 14" long, raised mound with trench as per instructions.

-----  
BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1102, surveyed July/Aug. 1982 - (DCSO records Vol. 46 Page(s) 17600)

-----  
Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 24" long, 3/4" dia., 48" in the ground, with the top 24" below the surface, from which  
An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.16°E., 164 lks. dist., with brass cap mkd. T23S R7W S32 RM 1982 with an arrow pointing to the cor.  
An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.63½°W., 91 lks. dist., with brass cap mkd. T23S R7W S31 RM 1982 with an arrow pointing to the cor.  
An Iron post 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears N.61°W., 323 lks. dist. with brass cap mkd. T23S R7W S30 RM 1982 with an arrow pointing to the cor.  
The cor. is located in a tree seedling farm.