

PRIMARY CORNER DESCRIPTION Sec Cor for 19, 20, 29 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2491)

Set post cor. to secs. 19, 20, 29 and 30, on side of steep hill, from which
A Fir 8" dia., bears N.8°W., 474 lks. dist.
A W.Oak 12" dia., bears N.9°E., 476 lks. dist.
A B.Oak 3" dia., bears S.40°E., 34 lks. dist.
A W.Oak 3" dia., bears S.30°W., 18 lks. dist.

Douglas County Surveyors Office - Milo Godfrey and crew - C.S. File 52/125-29 - Jan. 1966

Corner searched for, not found.

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #987, surveyed July/Nov. 1979 - (DCSO records Vol. 42 Page(s) 16583-84)

From the point for the cor. of secs. 19, 20, 29 and 30, at proportionate distance; there is no remaining evidence of the original cor.

Set an iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 23 S R 7 W
S 19 | S 20
S 30 | S 29
1979

from which

- A Fir 16" dia., bears N.25°E., 25 lks. dist. mkd. T23S R7W S20 BT.
- A Fir 16" dia., bears S.86¼°E., 76 lks. dist. mkd. T23S R7W S29 BT.
- A Fir 14" dia., bears S.80 3/4°W., 27 lks. dist. mkd. T23S R7W S30 BT.
- A Fir 10" dia., bears N.83½°W., 41 lks. dist. mkd. T23S R7W S19 BT.

Fd. and used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1102, surveyed July/Aug. 1982 - (DCSO records Vol. 46 Page(s) 17600)