

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 200328

PRIMARY CORNER DESCRIPTION M.C. on East bdy sec. 19

Alias 869250 Description M.C. on right bank Umpqua River
Alias 043030 Description Point on N. bdy. DLC #43
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2494)

Right bank of Umpqua River, where marked a Fir 40" dia. for cor. to fractional secs. 19 and 20, from which
A B.Oak 36" dia., bears S.52°W., 64 lks. dist.
A B.Oak 15" dia., bears N.77°E., 100 lks. dist.

Douglas County Surveyors Office - Milo Godfrey and crew - C.S. File 52/125-42 - Jan. 1966

Corner searched for, not found.

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #987, surveyed July/Nov. 1979 - (DCSO records Vol. 42 Page(s) 16587)

Point for the meander cor. bet. secs.19 and 20, on the right bank of the Umpqua River, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.