

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2495)

Set post cor. to secs. 17, 18, 19 and 20, from which
A Fir 9" dia., bears S.27°W., 29 lks. dist.
A W.Oak 6" dia., bears N.66°W., 25 lks. dist.
A W.Oak 10" dia., bears N.27°E., 20 lks. dist.
A B.Oak 12" dia., bears S.46°E., 32 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Nov. 9, 1960 - C.S. 49/49-10

Found - Orig. 9" now 36" Fir stump S.27°W., 19.1 ft. BT previously opened, shows good scribing "23 SW".
No trace of other orig. BTs.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 7 W
S 18 | S 17
S 19 | S 20
1960

Corner is 18 ft. North of fence corner, running N.; S.; and West.

New BTs- 14" W.Fir bears N.52°W., 16.3 ft. scribed S18 T23S
R7W CS BT.
28" Maple bears S.65°W., 36.6 ft. scribed S19 T23S
R7W CS BT.
16" R.Fir bears S.20°E., 38.0 ft. scribed S20 T23S
R7W CS BT.
18" Maple bears N.44°E., 25.0 ft. scribed S17 T23S
R7W CS BT.

BLM resurvey by Floyd A. Brooks and Peter A. Peterson, Cadastral Surveyors, under Group #594 - Surveyed Aug/Sept 1965 - (DCSO records Vol. 33 Page(s) 13894-95)

The Sec. Cor., remonumented by Byron in 1960, with an iron post 1" dia., firmly set, projecting 14" above ground with brass cap mkd. in 1960, from which an original bearing tree:
A sawed Fir stump 36" dia., bears S.27°W., 29 lks. dist., with scribe marks 23S W S19 visible on opened blaze.

and bearing trees mkd. by Byron:

A Maple 17" dia., bears N.44°E., 37½ lks. dist., with scribe marks T23S R7W S17 CS BT.

A Fir, snag, 17" dia., bears S.20°E., 57 lks. dist., with fragmentary scribe marks visible on pitched over double blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A Maple 30" dia., bears S.66°W., 55½ lks. dist., with scribe marks T23S R7W S19 CS BT.
A W.Fir snag, 17" dia., bears N.52°W., 24½ lks. dist. with scribe marks T23S R7W S18 CS BT visible on unhealed double blaze.
and new bearing trees:
A W.Fir 18" dia., bears N.8°E., 159 lks. dist. mkd. T23S R7W S17 BT.
A Fir 4" dia., bears S.28¼°E., 26 lks. dist. mkd. T23S R7W S20 BT.
A W.Fir 24" dia., bears N.7°W., 118 lks. dist. mkd. T23S R7W S18 BT.
The corner falls on ridge, bears N.10°E. and S.10°W.

Fd. and used in BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #987, surveyed July/Nov. 1979 - (DCSO records Vol. 42 Page(s) 16587-88)

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda 5/15/2008 - C.S. File 67/25-49

Found - 1960 brass cap 2½" in dia. (properly) mkd. on a 1½" O.D. IP firmly set & protruding approx. 15" above ground.
Remains of one orig. BT fd. A shattered, rotted Fir stump of 30+" dia. (measurement at ground level) showing evidence of old blaze healing scars & old axe marks; bears S.27°W., 19.1 ft. as per rec.
From the 1960 DCSO renewal evidence of two BT FD:
A 28" maple now a shattered approx. 20" DBH Maple with upper portion & scribed lower trunk fallen face down toward corner; bears S.65°W., 36.6 ft. (as per record)
A 16" R.Fir now a 20" dia., 1½ ft. tall D.fir stump with evidence of healed blaze & partial reverse scribing, bears S.20°E., 38.0 ft. (as per rec.)
From the 1965 BLM Renewal evidence of 2 BTs fd:
A fir 4" dia., now a 24" dia., 1.8 ft tall D.Fir stump showing evidence of a fully healed double blaze, bears S.28¼°E., 17.2 ft. (as per rec)
A W.Fir 24" dia., now 35" DBH W.Fir with a fully healed double blaze bears N.7°W., 77.9 ft. (as per rec.)

New - An 8" DBH Maple scribed "T23S R7W S19 CS BT" on a double blaze, bears S.5¾°W., 86.1 ft.
A 12" DBH D.Fir scribed "T23S R7W S19 CS BT" on a double blaze, bears S.66½°W., 7.3 ft.

continued next page

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 13" DBH D.Fir scribed "T23S R7W S19 CS BT" on a double blaze, bears S.83½°W., 25.5 ft.

Note - Monument is near crest of a NE-SW running ridge & just southerly of saddle in ridge. Monument is just west of top of cut-bank of a logging rd. which is running generally north-south locally. Large clear-cuts to east & northeast. Compass decl. 16¼°E.

Fd. Ok by C. Sweeden, 4/2008 - M156-11