

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2483)

Set 1/4 sec. post, from which
A B.Oak 18" dia., bears S.36°W., 80 lks. dist.
A B.Oak 10" dia., bears S.41°E., 58 lks. dist.

Survey by Francis E. Waggoner - For: Puget Timber Co. - Completed July 6, 1955 - C.S. File 42/1

After diligent search, I am unable to find any trace of 1/4 corner or BTs. At proportionate point:
Set 5/8" iron rod, treated 2" x 4" x 4 ft. post "1/4S", from which
10" Fir bears N.47°10'E., 59.7 ft. "1/4 S21 BT" on blaze.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group # 518 - surveyed June/July 1963 - (DCSO records Vol. 31 Page(s) 13165)

The 1/4 sec. cor., reestablished and recorded by Waggoner in 1955, monumented with a steel rod, 5/8" dia., 18" long, firmly set 14" in the ground, from which the Waggoner bearing tree:
A Fir 16" dia., bears N.47°E., 93 lks. dist., with a healed blaze breast high.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd: 1/4
S 20 S 21
T 23 S R 7 W
1963
from which a new bearing tree:
A double W.Oak 5" dia., bears N.1 1/4°W., 144 lks. dist. mkd. 1/4 S20 BT.
Deposit the steel rod alongside the iron post.

Fd. Ok by L.Roberts, June 1997 - 1997-0078