

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2488)

Set ¼ sec. post, from which
A Fir 25" dia., bears N.4°E., 50 lks. dist.
A Fir 35" dia., bears S.4°W., 100 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1965 - C.S. File 52/125-19

Found - Orig. 25" now 54" Fir, N.4°E., 33.0 ft., shows "4 S", bark scribe in very poor condition.
No trace of other BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 7 W
¼ S5 | S4
1965

New BTs- 8" Myrtle N.67°E., 6.7 ft. mkd. ¼ S4 CS BT.
15" D.Fir S.51°W., 24.6 ft. mkd. ¼ S5 CS BT.
Corner lies on very steep SE. slope of river bluffs.

Fd. BC & record BTs by C. Woodruff, 1/2012 - M163-30A-C