

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2484)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.43°W., 51 lks. dist.
A Fir 7" dia., bears N.34°E., 13 lks. dist.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #330, Surveyed Aug. 1957 (DCSO records Vol. 28 Page(s) 12094)

The ¼ sec. cor., determined by reference to the remaining original bearing tree:

A Fir 36" dia., bears N.34°E., 13 lks. dist.; I find no scribe marks after opening scars which appear to be upper and lower blazes cut into about 40 years ago and again overgrown after being burned; according to a signed statement furnished me by Frank Kausche, hereto appended, the scribe marks were visible at that time. I accept this tree as the best available evidence of the original corner.

At the corner point

Set an iron post, 30" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 7 W
 S 16
 ¼ S 21
 1957

from which new bearing trees:

A Fir 6" dia., bears N.46½°W., 32 lks. dist. mkd. ¼ S16 BT
A Fir 16" dia., bears S.35°W., 40 lks. dist. mkd. ¼ S21 BT

Fd. OK, Jan. 1994 by D. Bentz - M 119-24