

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GL0 survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCS0 records Vol. 6 Page(s) 2478)

Set post cor. to secs. 3, 4, 9 and 10, from which
A B.Oak 14" dia., bears S.32°W., 64 lks. dist.
A W.Oak 15" dia., bears N.11°W., 97 lks. dist.
A W.Oak 15" dia., bears N.75°E., 153 lks. dist.
A W.Oak 24" dia., bears S.8°E., 75 lks. dist.

George C. Baker - Myrtle Creek, Oregon - (Record source not found - former renewal #11)

Set a 3/4" x 50" Iron axle with gear on top 36" in ground.
Found the original bearing trees as follows:
24" W.Oak S.8°E., 75 lks.
W.Oak N.75°E., 153 lks., down and rotting.
W.Oak S.32°W., 64 lks., down and rotting.
Marked new bearing trees as follows:
24" Fir N.15°E., 39.2 ft.
10" Cedar N.34°34'W., 42.0 ft.
8" Fir S.67°15'E., 8.2 ft.
28" Fir S.48°40'W., 9.6 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - June 4, 1958 - C.S. File 49/49-2

Found - 1" Iron axle gear on top at corner.
24" W.Oak, orig., now shows old face, now rotted, no scribing visible, N.8°E., 49.5 ft.
Found all of Baker's BTs, now snags or stumps. All check for bearing and distance and all show scribing.
New BTs- 14" W.Fir bears N.69°W., 45.0 ft. scribed S4 T23S R7W CS BT.
12" Myrtle bears N.24°E., 73.3 ft. scribed S3 T23S R7W CS BT.
16" R.Fir bears S.51½°W., 48.0 ft. scribed S9 T23S R7W CS BT.
36" W.Oak bears S.8°E., 50.5 ft. scribed S10 T23S R7W CS BT.