

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2472)

-----  
Set ¼ sec. post, from which  
A Fir 14" dia., bears N.5°W., 14 lks. dist.  
A Laurel 4" dia., bears S.30°W., 20 lks. dist.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #456, Surveyed Aug 1961/Jan. 1962 (DCSO records Vol. 31 Page(s) 13079-80)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, to solid rock, with brass cap mkd: ¼  $\frac{S\ 27}{S\ 34}$   
T 23 S R 7 W  
1961

from which  
A Chinquapin 15" dia., bears N.60½°E., 70 lks. dist. mkd. ¼ S27 BT.  
A Fir 18" dia., bears S.72½°E., 170 lks. dist. mkd. ¼ S34 BT.

Mark Smalley - For: Riverbend Resources - June 1998 - M 129-30-

-----  
Found - 1961 BLM brass cap on iron pipe.  
21" Chinquapin, N.60½°E., 46.2 ft., healed.  
29" Fir, S.72½°E., 112.2 ft., healed.  
Scribed- 16" Fir, S.22°E., 21.8 ft., "¼ S BT"  
14" Fir, N.71°E., 34.1 ft., "¼ S BT"  
Corner falls at the end of old logging road.