

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2518)

Set Dogwood for the ¼ sec. cor., from which
A Dogwood 10" dia., bears S.30°E., 30 lks. dist.
A Maple 14" dia., bears S.80°W., 54 lks. dist.

Claude Kerr, Eng. #2125 - Corner report filed March 1949 - C.S. File 40/190

Found - Maple with grown over face.
Dogwood marked ¼ S.
Set 3" x 4 ft. W.Fir stake.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy and crew - March 23, 1964 - C.S. File 52/125-8

Found - 20" Maple S.80°W., 35.6 ft., opened and found good scribing "BT".
18" Dogwood S.30°E., 19.8 ft., part of old face visible, badly rotted, part of "S" visible.
Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 7 W
¼ S26 | S25
1964
New BTs- 53" D.Fir N.60°E., 78.3 ft. mkd. ¼ S25 CS BT.
15" Red Cedar N.27°W., 96.7 ft. mkd. ¼ S26 CS BT.
Corner lies on very steep North slope.

David Edwards - For: Roseburg Resources Co - 4/2006 - M150-27

Found - 24" Maple S.80°W., 35.6'
53" Fir stump N.60°E., 78.3'
New - 9" Fir S.47°E., 6.7'
6' steel post 2' north.