

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13; & 18 of T23-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 6 Page(s) 2392)

Set Fir post for ¼ sec. cor., from which
A Cedar 24" dia., bears N.40°E., 14 lks.
A Cedar 14" dia., bears S.85°W., 5 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12654)

The ¼ sec. cor., determined from the original bearing trees:
A Cedar 30" dia., bears N.40°E., 5 lks., with healed blaze
A Cedar 22" dia., bears S.85°W., 14 lks. dist., with marks
BT on exposed face.

At the corner point
Set an iron post, 3 ft. long, 2" dia., 30" in the ground,
with brass cap mkd:
T23S
¼
R7W|R6W
S13|S18
1957

from which
A Fir 12" dia., bears S.39°E., 51 lks., mkd. ¼ S18 BT.
A Fir 20" dia., bears S.39½°W., 43 lks., mkd. ¼ S13 BT.

David Edwards - Oct. 2011 - C.S. File 65/72-34

Found - 1957 BLM brass cap projecting 2" above ground. The cap is oriented 180° from normal.
20" Fir capped stump bears S.39½°W., 28.4 ft. Scribing visible.
Fir to SE completely missing.
North-South fence around BLM reprod. is 6' West.
New BTs- An 11" dia. Fir scribed "¼ S18 BT" bears N.7°E., 38.2 ft.
An 8" dia. Fir scribed "¼ S13 BT" bears N.87°W., 15.2 ft.
Set a 6 ft steel post 2 ft to the North.