

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only (West)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2544)

Set a stone 16x10x6 ins., 10" in the ground for cor. to secs. 30 and 31, marked with 1 notch on S. and 5 notches on N. edges, from which

A Fir 5" dia., bears N.41°E., 5 lks. dist. mkd. T23S R8W S30 BT.

A Fir 10" dia., bears S.61°E., 21 lks. dist. mkd. T23S R8W S31 BT.

A Fir 14" dia., bears S.54°W., 115 lks. dist. mkd. T23S R8W S30 & 31 BT.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #688 dated June 9, 1898 (DCSO records Vol. 6 Page(s) 2616)

The cor. of secs. 30 & 31, which is a sandstone 10x6 ins., 6" above ground, marked and witnessed as described by the surveyor general. I destroyed all marks at old cor. referring to secs. 25 and 36.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1967 - C.S. File 54/12-8

Found - Sandstone 16x6x8", firmly set but covered 6" deep with loose dirt and mkd. with 1 notch on S. and 5 notches on N. edges.

Orig. 5" now 18" Fir, alive, N.41°E., 3.3 ft., shows good scar. Rescribe "T23S R8W S30 CS BT"

Orig. 10" now 30" Fir, alive, S.61°E., 13.9 ft., shows fair scar. Rescribe "T23S R8W S31 CS BT"

Orig. 14" now 39" Fir, alive, S.54°W., 75.9 ft., shows good scar. Do not open

Set brass cap at cor. mkd. County Surveyors Office

R	T 23 S	R
9	S 30	8
W	S 31	W
	1967	

Reset stone alongside.

This corner lies on E. edge of small creek, course S.10°E.