

PRIMARY CORNER DESCRIPTION E. 1/4 cor. for Sec. 12 only, T23-9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 279, dated March. 5, 1878 - (DCSO records Vol. 6 Page(s) 2537)

Set a Fir post 4" dia., 4 ft. long, 18" in ground for ¼ sec. corner, from which

A Fir 8" dia., bears S.30°E., 18 lks. dist.

A Fir 6" dia., bears N.70°W., 5 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2549)

The old ¼ sec. cor. on E. bdy. of Sec. 12, T23S R8W. The post being gone and the BTs greatly decayed, I reestablished the corner by setting a post 3 ft. long, and 3" sq., 2 ft. in the ground marked ¼ S on W. face, from which

A Fir 24" dia., bears N.48°E., 21 lks. dist. which I marked ¼ S BT.

A Fir 10" dia., bears S.52°W., 45 lks. dist. which I marked ¼ S BT.

BLM Resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, Surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16849)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S
R 9 W R 8 W
1/4 S 12
1980

from which

A Fir 11" dia., bears S.56 3/4°W., 50 lks. dist. mkd. X BT

A Fir 14" dia., bears N.42 3/4°W., 21 lks. dist. mkd. ¼ S12 BT.

Mark Smalley - For: Riverbend Resources - Oct. 1997 - M 124-64

Fd. -1980 Cadastral Brass cap on iron pipe.

BTs -18" Fir, S.56 3/4°W. 33.0' healed.

21" Fir, N.42 3/4°W., 13.9', healed.

New BTs -

20" Fir, S.56°E., 45.1', scribed "¼ S12 BT"

22" Fir, N.24°E., 10.2', scribed "¼ S12 BT"