

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2602)

-----  
A stone in place 16 x 10 x 6 ins., above ground, which I mark  $\frac{1}{4}$  on N. side with a cross (X) at exact point for  $\frac{1}{4}$  sec. cor., from which

A Hemlock 20" dia., bears N.69°E., 19 lks. dist. mkd.  $\frac{1}{4}$  S BT.

A Cedar 14" dia., bears S.48°E., 37 lks. dist. mkd.  $\frac{1}{4}$  S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct. 24, 1967 - C.S. File 54/12-69

-----  
Found - Orig. corner stone in place & mkd. "X and  $\frac{1}{4}$ "  
Orig. 20" now 28" Hemlock N.69°E., 12.5 ft., down with "4" scribe visible on open blaze.

Orig. 14" now 26" Cedar snag, S.48°E., 24.4 ft., shows scar. Do not open.

Set Brass cap at cor. mkd: County Surveyors Office  
(Reset rock alongside)

T 23 S R 8 W

$\frac{1}{4}$   $\frac{S}{S}$   $\frac{19}{30}$

1967

New BTs- 7" Hemlock S.9°W., 10.4 ft. mkd.  $\frac{1}{4}$  S30 CS BT.

16" Cedar N.2°W., 49.5 ft. mkd.  $\frac{1}{4}$  S19 CS BT.

Corner lies on NE. slope of spur, sloping N.