

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2604-05)

A stone in place, 24" x 24" x 12", above ground which I mark 1/4 with a cross (X) at exact cor. point for 1/4 sec. cor., from which
A Fir 20" dia., bears S.5°W., 16 lks. dist. mkd. 1/4 S BT
A Fir 24" dia., bears N.75°W., 17 lks. dist. mkd. 1/4 S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Feb/March 1967 - C.S. File 54/12-30

Found - Orig. sandstone 24" x 18" x 12" and marked "X 1/4".
Tipped out of place.
Orig. 20" now 30" Fir, alive, S.5°W., 10.6 ft., shows good scar. Do not open.
Orig. 24" now 36" Fir, alive, N.75°W., 11.2 ft. Open and find "4S" scribe and reverse.
Set Brass cap at cor. mkd: County Surveyors Office
(Reset rock alongside) T 23 S R 8 W
1/4 S 18
S 19
1967
New BTs- 30" D.Fir S.32°E., 22.2 ft. mkd. 1/4 S19 CS BT.
5" Hemlock N.75°E., 22.4 ft. mkd. 1/4 S18 CS BT.
Corner lies 1 ch. W. of ravine, course South.