

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2597-98)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 29, 30, 31 and 32 marked T23S S29 on NE.; R8W S32 on SE.; S31 on SW.; and S30 on NW. faces, with 1 notch on S. and 5 notches on E. edges, from which
A Hemlock 12" dia., bears N.55°E., 26 lks. dist. mkd. T23S R8W S29 BT.
A Fir 60" dia., bears S.39°E., 51 lks. dist. mkd. T23S R8W S32 BT.
A Hemlock 18" dia., bears S.35°W., 31 lks. dist. mkd. T23S R8W S31 BT.
A Hemlock 12" dia., bears N.12°W., 32 lks. dist. mkd. T23S R8W S30 BT.

Douglas Co. Surveyors Office - Gary L. Langlitz; P. Earle, crew - May 20, 1974 - C.S. File 56/51-11

Found - Orig. 18" now 30" Hemlock stob, rotten with scribing "2 R 8" visible on unhealed blaze.
Orig. 12" now 30" Hemlock, we open and find scribe marks.
We do not find adequate evidence to verify the remaining two original bearing trees.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
S 30 | S 29
S 31 | S 32
1974

from which
An orig. 18" now 30" rotten Hemlock stob with scribing visible bears S.35°W., 20.5 ft.
An orig. 12" now 30" Hemlock bears N.55°E., 17.2 ft.
We open and find scribe marks.
New BTs- 15" Hemlock bears S.84°E., 50.2 ft. scribed "T23S R8W S32 CS BT.
22" Hemlock bears S.65°W., 62.3 ft. scribed "T23S R8W S31 CS BT.
14" Hemlock bears N.55½°W., 37.8 ft. scribed T23S R8W S30 CS BT.