

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2605)

Set post 3 ft. long, 3" sq., 2 ft. in the ground for ¼ sec. cor. marked ¼ S on W. side, from which
A Fir 40" dia., bears N.26°W., 45 lks. dist. mkd. ¼ S BT
A Fir 40" dia., bears S.74°E., 33 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1966 - C.S. File 54/12-38

Found - Orig. 40" now 48" Fir stump N.26°W., 29.7 ft., previously opened and shows "¼S" scribe on burned face.
Orig. 40" now 48" Fir stump S.74°E., 21.8 ft. Do not open, cut low, probably no scribe left.
Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
¼ S18|S17
1966
New BTs- 8" D.Fir S.9°W., 18.1 ft. mkd. ¼ S18 CS BT.
13" Hemlock S.16½°E., 54.0 ft. mkd. ¼ S17 CS BT.
Corner lies on steep, East slope, approx. 100 ft. North of top of ridge, course NW. and SE.

Fd. and used in BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #1005, surveyed July/Dec. 1980 - (DCSO records Vol. 43 Page(s) 16828)