

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2608)

Set a post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 5, 6, 7 and 8, marked T23S S5 on NE.; R8W S8 on SE.; S7 on SW.; and S6 on NW.; faces with 5 notches on E. and S. faces, from which

- A Fir 50" dia., bears N.1°E., 22 lks. dist. mkd. T23S R8W S5 BT.
- A Chittem 4" dia., bears S.43½°E., 81 lks. dist. mkd. T23S R8W S8 BT.
- A Fir 24" dia., bears S.31°W., 30 lks. dist. mkd. T23S R8W S7 BT.
- A Fir 24" dia., bears N.79°W., 48 lks. dist. mkd. T23S R8W S6 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1966 - C.S. File 54/12-46

Found - Unrecorded 1½" I.P. with cast iron cap blazed on top and marked.
Orig. 50" Fir, N.1°E., 14.5 ft., face. Find old axe mark in remains of bark at base of badly decayed stump.
Orig. 24" Fir S.31°W., 19.8 ft., to hole, remains of turned out tree. No scribe found.
Orig. 24" now 30" Fir, badly decayed stump N.79°W., 31.7 ft., face, find "BT" barks scribe in very poor condition at base of stump.

No trace of BT to SE.
New BTs- 17" R.Cedar N.45°E., 17.9 ft. mkd. T23S R8W S5 CSBT
13" D.Fir N.56°W., 17.3 ft. mkd. T23S R8W S6 CS BT.
17" Hemlock S.11°W., 13.8 ft. mkd. T23S R8W S7 CS BT
14" D.Fir S.75°E., 15.0 ft. mkd. T23S R8W S8 CS BT.
Corner lies approx. 100 ft. South of road, course E-W.

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #1005, surveyed July/Dec. 1980 - (DCSO records Vol. 43 Page(s) 16831-32)

The Sec. cor., perpetuated and recorded by Tracy in 1966, monumented with an iron post 1½" dia., loosely set, with iron cap mkd. S5 S6 S7 S8, from which the remains of the original bearing trees:
(Cont. Next Page)

