

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 238700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only, T22-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 4 Page(s) 1593)

Set Fir post for ¼ sec. cor. from which
A Fir 18" dia., bears South, 9 lks.
A Fir 40" dia., bears N.30°E., 27 lks. dist.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #436, Surveyed May/June 1962 (DCSO records Vol. 31 Page(s) 13106)

The ¼ sec. cor, determined at record distance from the original bearing trees:

A Fir 52" dia., bears N.35°E., 27 lks. dist. with no marks remaining on badly scaled bark blaze.

A Fir 28" dia., bears South, 9 lks. dist. with scribe marks ¼ S BT visible on the bark.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 8 W

¼ S 32

T 23 S

1962

from which new bearing trees

A Chinquapin 5" dia., bears N.46½°E., 48½ lks. dist. mkd. ¼ S32 BT.

A Fir 6" dia., bears N.15¼°W., 37 lks. dist. mkd. ¼ S32 BT.

Fd. OK, June 10, 1982, R.R. Luckman, M 92-54