

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2606)

Set post 3 ft. long, 3" sq., 2 ft. in ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 50" dia., bears N.59°W., 92 lks. dist. mkd. ¼ S BT
A Fir 60" dia., bears S.48°E., 32 lks. dist. mkd. ¼ S BT

BLM dependent resurvey by Joseph S. Gawron under Group #350 surveyed June 1958 (DCSO records Vol. 33 Page(s) 13834-35)

The ¼ sec. cor., monumented with an iron pipe 2" dia., set 18" in the ground, firmly set, from which the remains of the original bearing trees:

A Fir stump 50" dia., bears S.84°E., 32 lks. dist., no marks remaining. (Rec. brg. S.48°E.)

A stump hole, bears N.59°W., 92 lks. dist.

Add two additional accessories:

A Fir stump 50" dia., bears S.17°W. mkd. RP ¼ SB/17.

A Fir stump 50" dia., bears N.23°W., with dim scribe marks on weathered face.

Each of these stumps is also marked with a rusted and scorched metal General Land Office Location post and a General Land Office Warning to Trespasser poster.

At the corner point

Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 8 W
¼ $\frac{S \ 8}{S \ 17}$
1958

from which

A Hemlock 6" dia., bears N.8°E., 88 lks. dist. mkd. ¼ S8 BT.

A Hemlock 20" dia., bears S.82½°W., 211 lks. dist. mkd. ¼ S17 BT.

Reset the iron pipe alongside the iron post.

Corner falls on a steep W. slope, on the edge of timber, bearing E. and W.

Douglas Co. Surveyors Office - John M. Powell and crew - March 16, 1973 - C.S. File 56/25-15

CORNER REPORT ONLY

Found - 6" Hemlock N.8°E., 58.6 ft. scribed ¼ S8 BT

20" Hemlock S.73°W. (Rec. S.82½°W.) 139.1 ft. scribing visible.

(Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1958 GLO brass cap at corner
Also found 1½" I.P. alongside as noted in resurvey notes.

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #1005, surveyed July/Dec. 1980 - (DCSO records Vol. 43 Page(s) 16829)

The ¼ sec. cor., monumented with an iron post 2½" dia., firmly set, projecting 10" above ground, with brass cap mkd. in 1958, from which the remains of the original bearing trees:

- A Fir stump 50" dia., bears S.84°E., 32 lks. dist., no marks remaining.
- and the remains of a local bearing tree recorded by Gawron:
 - A Fir stump 50" dia., bears N.23°W., 36 lks. dist., with fragmentary scribe marks visible on opened blaze.
- and the remains of the bearing trees mkd. by Gawron:
 - A Hemlock snag, 9" dia., bears N.5°E., 88 lks. dist., with scribe markds ¼ S8 BT visible on open blaze. (Rec. N.8°E.)
 - A Hemlock 37" dia., bears S.74°W., 211 lks. dist., with fragmentary scribe marks visible on partially healed blaze. (Rec. S.82½°W.)
- and a new bearing tree:
 - A Yew 17" dia., bears N.15½°E., 58 lks. dist., mkd. ¼ S8 BT.