

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2609)

Set a stone 12 x 8 x 6 ins., 8" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which
A Fir 50" dia., bears S.28°E., 18 lks. dist. mkd. ¼ S BT
A Fir 40" dia., bears N.72°W., 65 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Dec. 1966 - C.S. File 54/12-40A

Looked for not found.

Clyde Mulkins, For: IP Timberlands Operating Co. LTD - Dec. 1995 - M 123-32

Found - The original ¼ corner position.
55" DF (uprooted and slid down hill) with visible scribes (S.28°E., 18 lks rec.)
45" DF stump with scribe fragments, bears N.72°W., 42.9'. (Rec. 65 lks)
A steel fence post (BLM's approx. ¼ corner) bears N.81°W., 10.4'.
Set 3¼" alum. cap on a 36" alum. rod, from which
40" DF, bears N.12°W., 27.1', scribed "¼ S5 BT"
34" DF, bears N.71°E., 27.4', scribed "¼ S5 BT"
11" DF, bears S.5°E., 18.8', scribed "¼ S8 BT"
10" DF, bears N.71°W., 33.4', scribed "¼ S5 BT"