

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2588-89)

Set post 4 ft. long, 4" sq., 2 ft. in the ground for cor. to secs. 20, 21, 28 and 29, marked T23S S21 on NE.; R8W S28 on SE.; S29 on SW.; and S20 on NW. faces, with 2 notches on S. and 4 notches on E. edges, from which
A Hemlock 24" dia., bears N.65°E., 26 lks. dist. mkd. T23S R8W S21 BT.
A Hemlock 12" dia., bears S.1°E., 17 lks. dist. mkd. T23S R8W S28 BT.
A Hemlock 10" dia., bears S.23°W., 17 lks. dist. mkd. T23S R8W S29 BT.
A Fir 60" dia., bears N.76°W., 69 lks. dist. mkd. T23S R8W S20 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1966 - C.S. File 54/12-53

Found - Orig. 60" now 76" Fir, N.76°W., 45.5 ft. Open and find "B" scribe and reverse, face apparently burned before blaze healed over.

No trace of other original bearing trees.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 8 W
S 20 | S 21
S 29 | S 28
1966

New BTs- 16" Hemlock N.79°W., 13.9 ft. mkd. T23S R8W S20 CSBT
12" Hemlock S.31½°W., 24.4 ft. mkd. T23S R8W S29 CS BT.

9" Hemlock S.25°E., 19.0 ft. mkd. T23S R8W S28 CS BT

16" Hemlock N.54°E., 26.3 ft. mkd. T23S R8W S21 CSBT

Corner lies on top of small spur, sloping to NW. in heavy timber.

BLM resurvey by John A. Farmer, Cadastral Surveyor, under Group #1336, Surveyed Aug/Oct. 1986 - (DCSO records Vol. 48 Page(s) 18288)

The sec. cor., perpetuated and recorded by Tracy in 1966, monumented with an iron post 1½" dia., firmly set, projecting 12" above ground with brass cap mkd. in 1966 from which an original bearing tree:

A Fir 78" dia., bears N.76°W., 65 lks. dist., with open blaze, no marks visible. (Rec. 69 lks.)

(Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and bearing trees mkd. by Tracy:

A Hemlock 21" dia., bears N.44½°E., 41 lks. dist., with healed blaze.

A Hemlock 10" dia., bears S.27½°E., 29 lks. dist., with healed blaze.

A Hemlock 10" dia., bears S.31°W., 37 lks. dist., with scribe marks T23S R8W S29 CS BT visible on open blaze.

A Hemlock 22" dia., bears N.79°W., 21 lks. dist., with healed blaze.

and a bearing tree of no record:

A Hemlock 22" dia., bears S.15 3/4°E., 12 lks. dist., with healed blaze.