

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCS0 records Vol. 6 Page(s) 2590-91)

-----  
Set post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 16, 17, 20 and 21, marked T23S S16 on NE.; R8W S21 on SE.; S20 on SW.; and S17 on NW. faces, with 3 notches on S. and 4 notches on E. edges, from which  
A Fir 6" dia., bears N.40°E., 58 lks. dist., mkd. T23S R8W S16 BT.  
A Fir 24" dia., bears S.82°E., 105 lks. dist. mkd. T23S R8W S21 BT.  
A Fir 40" dia., bears S.24°W., 33 lks. dist. mkd. T23S R8W S20 BT.  
A Fir 30" dia., bears N.18°W., 79 lks. dist. mkd. T23S R8W S17 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1966 - C.S. File 54/12-37

-----  
Found - Orig. 40" now 60" Fir, S.24°W., 21.8 ft. Open and find "8" scribe and reverse.  
Orig. 30" now 50" Fir, N.18°W., 52.1 ft., shows scar. We do not open.  
No trace other original BTs.

Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 8 W  
S 17 | S 16  
S 20 | S 21  
1966

New BTs- 13" Hemlock S.21°E., 19.4 ft. mkd. T23S R8W S21 CS BT.  
24" Hemlock N.61°E., 19.1 ft. mkd. T23S R8W S16 CSBT  
16" Hemlock N.37½°W., 22.2 ft. mkd. T23S R8W S17 CS BT.  
11" Hemlock S.59°W., 14.9 ft. mkd. T23S R8W S16 CSBT  
Corner lies 30 ft. North of road on top of ridge.

Fd. OK, March 1971 by DCS0, J. Powell - C.S. File 54/12-71

Clyde Mulkins - For: IP Timberlands - March 1995/May 2015 - M169-50 (filed 7/2/2015)

-----  
Found - A 3" 1966 County brass cap at the corner from which:  
A 60" DF stump with opened face bears S.24°W. 21.8 FT  
A 50" DF stump with scar bears N.18°W. 52.1 ft.  
A 17" Hemlock stump with visible scribes bears S.21°E. 19.4 ft. continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

A 28" Hemlock stump with scribes bears N.61°E. 19.1 ft  
A 20" Hemlock stump with scribes bears N.37½°W. 22.2 ft.  
A 14' Hemlock stump with scribes bears S.59°W. 14.9 ft.  
Corner falls 30 ft. North of paved ridge top road.

Ronald L. Rice, Ward NW - Sept. 2010 - C.S. File 65/69-52  
-----  
Found - 2½" Douglas County brass cap dated 1966 with the following accessories:  
60" D.Fir stump bears S.24°W., 21.8' - open rotted face  
50" D.Fir stump bears N.18°W., 52.1' - healed face  
Rotted Hemlock stump of indeterminate dia. bears N.61°E., 19.1' - no marks.  
Rotted Hemlock stump of indeterminate dia. bears S.59°W., 14.9' - no marks.  
New - 17" D.Fir bears S.61°E., 10.5' - blazed, scribed "T23S R8W S21 BT"  
15" D.Fir bears S.55°W., 15.7' - blazed, scribed "T23S R8W S20 BT"  
13" D.Fir bears N.65°W., 16.0' - blazed, scribed "T23S R8W S17 BT"  
14" D.Fir bears N.23°E., 22.4' - blazed, scribed "T23S R8W S16 BT"  
Note - Corner has steel cost adjacent to it. All BTs have red painted bands and yellow tags.  
Compass decl. 16°E.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCS0 records Vol. 58 Page(s) 23413-4)  
-----  
The cor. of secs. 16, 17, 20, and 21, perpetuated by the Douglas Co Surveyor's Office in 1966; further perpetuated by Rice, in 2010; monumented with an iron post, 2" dia., firmly set, projecting 11" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees  
A decayed fir stump, 65" dia., bears S.24°W., 17.2 ft., with no marks visible on open blaze. (Record and slope, 21.8 ft.)  
A decayed fir stump, 58" dia., bears N.18°W., 52.1 ft., no marks visible.  
and the remains of the BTs mkd. by the Douglas Co Surveyor's Office  
A decayed hemlock stump, size indeterminate, bears N.61°E., 22.2 ft., no marks visible. Replace tin cap found lying alongside.  
A decayed hemlock stump, size indeterminate, bears S.60½°W., 11.4 ft., with remains of a healed blaze.  
continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the bearing trees mkd. by Rice  
A fir, 17" dia., bears N.24°E., 22.4 ft., with illegible scribe marks visible on partially healed blaze and a nail at the base on the right side center.  
A fir, 19" dia., bears S.51½°E., 10.5 ft., with a healed blaze and a nail at the base on the left side center.  
A fir, 18" dia., bears S.55¼°W., 15.6 ft., with illegible scribe marks visible on partially healed blaze and a nail at the base on the right side center.  
A fir, 15" dia., bears N.66°W., 16.0 ft., with a healed blaze and a nail at the base on the left side center.  
An aluminum fence post is alongside the cor.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorusung- 7/20/2021 (Filed 4/7/2022) - C.S. File 67/51-29

-----  
Fd. OK  
Lat: 43°34'37.66"N Long: 123°39'49.96"W