

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2593)

-----  
 Set a post 4 ft. long, 4" sq., 2 ft. in the ground for cor. to secs. 8, 9, 16 and 17, mkd. T23S S9 on NE.; R8W S16 on SE.; S17 on SW.; and S8 on NW. faces with 4 notches on S. and E. edges, from which  
 A Fir 10" dia., bears N.22°E., 11 ks. dist. mkd. T23S R8W S9 BT.  
 A Fir 10" dia., bears S.40°E., 33 lks. dist. mkd. T23S R8W S16 BT.  
 A Fir 24" dia., bears S.53½°W., 47 lks. dist. mkd. T23S R8W S17 BT.  
 A Hemlock 20" dia., bears N.30°W., 14 lks. dist. mkd. T23S R8W S8 BT.

BLM dependent resurvey by Joseph S. Gawron under Group #350 surveyed June 1958 (DCSO records Vol. 33 Page(s) 13834)

-----  
 The sec. corner, monumented with an iron pipe 2" dia., set 20" in the ground, firmly set, from which the remains of the original bearing trees:  
 A Fir, dead and fallen, 18" dia., bears S.40°E., 33 lks. dist., with an exposed and burned face.  
 A Fir, dead and fallen, 30" dia., bears S.53½°W., 47 lks. dist., from which scribe marks are chopped out and exposed.  
 A stump, burned, bears N.30°W., 14 lks. dist.

At the corner point  
 Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:

T	23	S	R	8	W
	S	8	S	9	
	S	17	S	16	
					1958

from which  
 A Fir snag 50" dia., bears N.12°E., 228 lks. dist. mkd. T23S R8W S9 BT.  
 A W.Fir 7" dia., bears S.57½°E., 296 lks. dist. mkd. T23S R8W S16 BT.  
 A W.Fir 12" dia., bears S.26°W., 173 lks. dist. mkd. T23S R8W S17 BT.  
 A Fir stump 34" dia., bears N.15°W., 42 lks. dist. mkd. T23S R8W S8 BT.

Reset the iron pipe alongside the iron post.  
 Corner falls on a bench, which has been clear cut and burned.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Douglas Co. Surveyors Office - John M. Powell, J. Heritage, G. Commons, crew - March 16, 1973 - C.S. File 56/25-14</p> <p>-----</p> <p>Found - Orig. 30" Fir, now stump, S.53½°W., 31.0 ft. 1958 BT, 34" Fir stump, N.15°W., 27.7 ft. scribed T23S R8W S8 BT. 1958 BT, 50" Fir snag, N.12°E., 150.5 ft. 1958 GLO brass cap at section corner.</p> <p>New BTs- 6" W.Fir, S.74°E., 18.4 ft. scribed S16 CS BT. 6" D.Fir N.50°E., 11.3 ft. scribed S9 CS BT. 12" D.Fir N.42°W. 19.7 ft. scribed T23S R8W S8 CS BT 5" D.Fir S.3°W., 15.2 ft. scribed S17 CS BT.</p>
<p>Clyde Mulkins - For: IP Timberlands - March 1995/May 2015 - M169-50 (filed 7/2/2015)</p> <p>-----</p> <p>Found - A 3" 1958 BLM brass cap at the corner, from which: An 18" DF with a healed face bears N.42°W. 19.7 ft. A 13" DF with a healed face bears N.50°E. 11.3 ft. A 14" Hemlock with a healed face bears S.74°E. 18.4 ft. A 10" DF with a healed face bears S.3°W. 15.2 ft. 50" DF snag with visible scribes bears N.12°E. 150.5 ft. 23" GF with a healed face bears S.57½°E. 195.4 ft.</p>
<p>Ronald L. Rice, Ward NW - Feb. 18, 2009 - C.S. File 65/66-10</p> <p>-----</p> <p>Found - ¾" GLO brass cap dated 1958 with the following accessories: 44" D. Fir snag bears N.12°E. 150.5' visible scribing 17" Hemlock bears S.74°E. 18.4' healed face (Record W. Fir) 16" D.Fir bears N.50°E., 11.3' healed face 23" D.Fir bears N.42°W., 19.7' healed face 26" W.Fir bears S.57½°E., 195.4' healed face.</p> <p>Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags. Dec. 16°E</p>
<p>BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23415-6)</p> <p>-----</p> <p>The cor of secs 8, 9, 16, &amp; 17, perpetuated by the Douglas Co Surveyor's Office in 1973; monumented with an iron post, 2" dia., firmly set, projecting 9" above ground (alongside of which is an iron pipe, 2" dia., firmly set, projecting 13" above ground), with a brass cap (properly) mkd. cont.</p>

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the BTs mkd. by Gawron in 1958  
A fir snag, 42" dia., bears N.12°E., 150.5 ft., no marks visible.  
A white fir high stump, 26" dia., bears S.47½°E., 195.4 ft., with a healed blaze.  
A decayed white fir stump, size indeterminate, bears S.26°W., 114.2 ft., no marks visible.  
A decayed fir stump, size indeterminate, bears N.15°W., 27.7 ft., no marks visible.  
and the remains of the BTs mkd. by the Douglas Co Surveyor's Office and reported by Gawron  
A fir, 18" dia., bears N.51°E., 11.3 ft., with a healed blaze.  
A hemlock high stump, 17" dia., bears S.75°E., 18.5 ft., with a healed blaze. (Record, white fir.)  
A fir, 25" dia., bears N.41°W., 19.5 ft., with a healed blaze.  
and new accessories  
An iron rod, 30" long, 5/8" dia., set 27" in the ground for a reference monument, bears S.54°13'47"E, 29.93 ft., with aluminum cap mkd. RM T23S R8W S16 29.9 FT T0 COR 2015, and an arrow pointing to the cor.  
A fir, 19" dia., bears S.73°W., 44.2 ft., mkd. T23S R8W S17 BT.  
Corner is located on the NW. cor. of young fir reproduction, edge bears S. & E. A steel fence post is alongside the cor.  
NAD 1983 (2011)  
Latitude: 43°34'37.64"N. Longitude: 123°39'49.99"W.

FD OK DCS0 (SJF & JL) 7/20/2021 - C.S. File 67/51-12 - note:  
Fir snag, 42" dia., from 2015 renewal - now broken 15' tall.  
Lat: 43°34'37.62" N Long: 123°39'50.02 W