

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Pg 2595)

Set a stone 12 x 8 x 6 ins., 8" in the ground for 1/4 sec. cor. marked 1/4 on North face, from which
A Fir 14" dia., bears S.73°W., 34 lks. dist. mkd. 1/4 S BT.
A Fir 48" dia., bears N.53°E., 31 lks. dist. mkd. 1/4 S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Feb/March 1967 - C.S. File 54/12-25

Found - Stone 12x8x6 ins. sandstone at corner, no markings.
Orig. 14" Fir, now down, S.73°W., 22.4 ft. scribing "S"
Orig. 48" now 56" D.Fir N.53°E., 20.5 ft. scribing "/ 4S" on bark and good BT face.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
1/4 S 4
S 9
1967

New BTs- 6" D.Fir N.61 1/2°E., 46.5 ft. mkd. 1/4 S4 CS BT.
21" D.Fir S.79°W., 12.4 ft. mkd. 1/4 S9 CS BT.
Corner lies on steep South slope, approx. 200 ft. S. of ridge.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2772, surveyed Sept./Nov. 2014 - (DCSO records Vol. 58 Page(s) 23275-6)

The 1/4 sec. cor. of secs. 4 and 9, perpetuated the Douglas County Surveyor's Office in 1967; monumented with an iron post, 1 1/2" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree
A fir stump, 64" dia., bears N.53°E., 20.5 ft., no marks visible.

and the remains of the BTs mkd. by the DCSO
A fir high stump, 9" dia., bears N.61 1/2°E., 46.5 ft., with no scribe marks visible on partially healed blaze.
A pistol-butt fir snag, 20" dia., bears S.79°W., 12.4 ft., with illegible scribe marks visible on partially healed blaze.

and new bearing trees
A fir, 12" dia., bears N.65 1/4°E., 39.4 ft., mkd. 1/4 S4 BT.
A pistol-butt W.Fir, 12" dia., bears S.72°E., 11.9 ft., mkd. 1/4 S9 BT.