

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2575)

Set a post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 30" dia., bears N.34°W., 15 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.42°E., 47 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Feb. 1967 - C.S. File 54/12-23A

Looked for, not found.

Ronald L Rice - For: Rome Creek Timber 1 LLC - 6/2016 - M172-20

The ¼ corner was searched for, no evidence was found. The proportioned corner position fell on what is now a steep rock face which could not be occupied. The corner was not monumented at the request of the client.