

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2581)

Set post 3 ft. long, 3" sq., 2 ft. in ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Cedar 5" dia., bears S.73°E., 11 lks. dist. mkd. ¼ S BT
A Fir 9" dia., bears S.44°W., 20 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1966 - C.S. File 54/12-39

Found - Orig. 9" D.Fir, now rotted stump, S.44°W., 13.2 ft., unhealed face shows "¼S" scribe.

No trace of SE. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
¼ S16|S15
1966

New BTs- 20" D.Fir S.88°W., 22.3 ft. mkd. ¼ S16 CS BT.
22" I.Cedar N.80°E., 31.0 ft. mkd. ¼ S15 CS BT.

Corner lies on steep, South slope, approx. 300 ft. South of top of ridge, course E. and W.