

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2583-84)

-----  
Set a post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 3, 4, 9 and 10 mkd. T23S S3 on NE.; R8W S10 on SE.; S9 on SW.; and S4 on NW. faces, with 5 notches on S. and 3 notches on E. edges, from which  
A Fir 40" dia., bears N.58°E., 70 lks. dist. mkd. T23S R8W S3 BT.  
A Fir 24" dia., bears S.16°E., 12 lks. dist. mkd. T23S R8W S10 BT.  
A Fir 50" dia., bears S.35°W., 40 lks. dist. mkd. T23S R8W S9 BT.  
A Fir 10" dia., bears N.56°W., 18 lks. dist. mkd. T23S R8W S4 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew June 20, 1967 - C.S. File 54/12-58

-----  
Found - Orig. 40" now 48" Fir, alive, N.58°E., 46.2 ft., shows bark scribe.  
Orig. 24" now 28" Fir, alive, S.16°E., 7.9 ft., shows bark scribe.  
Orig. 50" now 54" Fir, alive, S.35°W., 26.4 ft., shows scribe and scar.  
Orig. 10" now 48" Fir, alive, N.56°W., 11.9 ft., shows bark scribe.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S R 8 W  
S 4 | S 3  
S 9 | S 10  
1967

Scribed orig. BTs:

Orig. 48" Fir N.56°W., 11.9 ft. remarked "T23S R8W S4 CS BT" in bark.  
Orig. 28" Fir, S.16°E., 7.9 ft. remarked "T23S R8W S10 CS BT" in bark.

New BTs- 7" D.Fir S.15°W., 26.8 ft. mkd. T23S R8W S9 CS BT.  
10" D.Fir N.17°E., 19.7 ft. mkd. T23S R8W S3 CS BT.  
Corner lies on top of spur sloping NW.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #640, surveyed July 1967/April 1968 (DCSO records Vol. 35 Page(s) 14441-42)

-----  
(Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3, 4, 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found 1967 brass cap, four orig. BTs and 2 BTs mkd. by Tracy.  
Add marks BLM 1967 to brass cap.

BLM Dependent resurvey by Edith M Forkner, Cadastral  
Surveyor, under Group #2772, surveyed Sept./Nov. 2014 -  
(DCSO records Vol. 58 Page(s) 23273)

-----  
The cor. of secs. 3, 4, 9, and 10, monumented with an iron  
post, 1½" dia., firmly set, projecting 16" above ground, with  
a brass cap (properly) mkd.

from which the remains of the original bearing trees

A roothole bears N.58°E., 40.9 ft., alongside of which is  
a down fir, 54" dia., no marks visible.

A roothole bears S.16°E., 9.9 ft., alongside of which is  
a down fir, 35" dia., with no scribe marks visible on  
decayed partially healed blaze.

and the remains of the bearing trees mkd. by the Douglas  
County Surveyor's Office in 1967

A fir, 25" dia., bears N.16°E., 19.8 ft., with a healed  
blaze.

A roothole bears S.16°W., 27.1 ft., alongside of which is  
a down decayed fir, 11" dia., no marks visible.

and new bearing trees

A fir, 8" dia., bears S.31½°E., 20.4 ft., mkd. T23S R8W  
S10 BT.

A fir, 8" dia., bears S.78°W., 11.6 ft. mkd T23S R8W S9 BT

A hemlock, 9" dia., bears N.30°W., 8.3 ft., mkd. T23S R8W  
S4 BT.