

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2578)

-----  
Set a sandstone 14x12x10 ins., 10" in the ground for ¼ sec. cor., mkd. ¼ on N. face, from which  
A Fir 16" dia., bears N.70°W., 10 lks. dist. mkd. ¼ S BT  
A Hemlock 12" dia., bears S.53°E., 24 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy, P. Earle, crew - June 10, 1974 - C.S. File 56/51-18

-----  
Found - Sandstone 10" x 12" x 14", firmly set with a "¼" plainly cut in the North face.

We also find the remains of two possible BTs:

An 18" rotten stob bears N.70°W., 6.6 ft., no markings found.

A 16" rotten stump bears S.50°E., 14.2 ft. (Rec. S.53°E., 15.8 ft.) No markings found.

The rotted condition of these two stumps makes a tree species determination impossible. We find this stone to be 164 ft. East of a stream, 1 lks. wide, course North. (Rec. 133.3 ft., East)

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S  
S 22 ¼  
S 27  
R 8 W  
1974

Deposit original stone alongside brass cap and mark the following BTs:

A 12" R.Cedar bears N.64½°E. 41.4 ft scribed "¼ S22 CS BT"

A 9" Hemlock bears S.31½°E., 3.0 ft. scribed "¼ S27 CS BT"

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23410)

-----  
The ¼ sec. cor. of secs. 22 and 27, perpetuated by Langlitz, Deputy Douglas County Surveyor, in 1974; monumented with an iron post, 1½" dia., firmly set, projecting 11" above ground (alongside of which is the original sandstone, 6x3", firmly set, projecting 6" above ground, with ¼ on the N. face), with a brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Langlitz  
A cedar snag, 12" dia., bears N.63¾°E., 41.5 ft., with scribe marks ¼ S22 CS visible on open double blaze.

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed hemlock stump, size indeterminate, bears S.38°E., 3.0 ft., no marks visible and the decayed hemlock log alongside.

and new bearing trees

A fir, 12" dia., bears N.2½°E., 10.9 ft., mkd. ¼ S22 BT.

A fir, 12" dia., bears S.10°E., 10.7 ft., mkd. ¼ S27 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center and has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. angle irons were driven alongside each corner unless an existing guard post was noted in the corner description.