

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2580)

Set a post 3 ft. long, 3" sq., 2 ft. in ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 16" dia., bears S.8°E., 34 lks. dist. mkd. ¼ S BT
A Maple 12" dia., bears N.63°W., 25 lks. dist. mkd. ¼ S BT

Survey by Les Roberts, LS #1039 - For: International Paper Co. Jan/Feb. 1981 - M 86-65

No evidence of original corner.
Set 1½" x 36" Iron pipe with brass cap at proportionate distance, from which
44" Fir bears S.18°W., 86.0 ft., scribed.
36" Fir bears N.77°W., 24.7 ft., scribed.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23412)

The ¼ sec. cor. of secs. 15 and 22, reestablished by proportionate measurement by Roberts, in 1981. There is no remaining evidence of the original cor., therefore this point is accepted as the cor.; monumented with an iron post, 1½" dia., firmly set, projecting 9" above ground, with a damaged brass cap (properly) mkd.
from which the remains of the bearing trees mkd. by Roberts
A decayed fir stump, 66" dia., bears S.18°W., 85.6 ft., no marks visible.
A burned decayed fir stump, 39" dia., bears N.79°W., 24.4 ft., with scribe marks ¼ S15 visible on open blaze at chest height and illegible scribe marks visible on partially healed blaze at base.
and new bearing trees
A fir, 7" dia., bears N., 30.6 ft., mkd. ¼ S15 BT.
A fir, 10" dia., bears S.49°W., 9.7 ft., mkd. ¼ S22 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center and has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. angle irons were driven alongside each corner unless an existing guard post was noted in the corner description.