

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2564)

Set a stone 16 x 14 x 4 ins., 12" in the ground for ¼ sec. cor. marked ¼ on W. face, from which
A Fir 4" dia., bears S.56½°W., 61 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.45°E., 24 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1966 - C.S. File 54/12-48

Found - Corner stone 16"x14"x4" mkd. "¼" on N. face.
Orig. 36" now 48" Fir, dead, N.45°E., 15.8 ft., open and find "4S" scribe on burned face.
Orig. 4" Fir now only rotted remains, S.56½°W., 40.3 ft. Find axe notch, no scribe.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
¼ S 34 | S 35
1966

New BTs- 10" Hemlock N.53°E., 29.8 ft. mkd. ¼ S35 CS BT.
7" D.Fir N.52°W., 16.7 ft. mkd. ¼ S34 CS BT.

Corner lies on gentle North slope, approx. 215 ft. S. of creek.

Fd. and used in BLM Resurvey by Stephen J. Malloy, Cadastral Surveyor, under Group #1219, Surveyed July/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18097-98)

Ron Quimby - For: Roseburg Resources Co. - 4/2018 - M174-23

Found - brass cap per 1966 renewal
48" rotten stump bears N.45°E 15.8' - open face
21" hemlock bears N.53°E., 29.8' - healed face
New BTs- 25" cedar bears S.21°E., 37.1' scribed "¼ S35 BT"
19" hemlock bears S.58°W., 10.1'
23" hemlock bears N.59°W., 54.1' both scribed "¼ S34 BT"