

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500578

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 and 10 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2573)

Set a post 4 ft. long,, 4" sq. for corner to secs. 2, 3, 10 and 11, mkd. T23S S2 on NE.; R8W S11 on SE.; S10 on SW.; and S3 on NW. faces, with 5 notches on S. and 2 notches on E. edges, from which

- A W.Fir 14" dia., bears N.32°E., 75 lks. dist. mkd. T23S R8W S2 BT.
- A Maple 6" dia., bears S.75°E., 41 lks. dist. mkd. T23S R8W S11 BT.
- A Fir 40" dia., bears S.55°W., 68 lks. dist. mkd. T23S R8W S10 BT.
- A Fir 10" dia., bears N.68°W., 22 lks. dist. mkd. T23S R8W S3 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam; S. Bilow, crew - July 1, 1959 - C.S. File 49/49-3

Found - Old Maple stump that checks bearing and distance for SE. BT.
Orig. 14" W.Fir now 32", shows old face, now rotted, N.32°E., 49.5 ft.
Orig. 40" now 56" Fir, S.55°W., 44.9 ft., shows good scars. I do not open.
Orig. 10" now 28" R.Fir N.68°W., 14.5 ft., shows scar. I do not open.
I also find rock set for closing corner, checks good for bearing and distance about 4 ft. less than record.

Set Brass cap at cor. mkd: County Surveyors Office
T 23 S R 8 W
S 3 | S 11
S 10 |
1959

New BTs- 10" R.Fir bears N.77°W., 36.3 ft. scribed S3 T23S R8W CS BT.
8" R.Fir bears S.72°W., 42.5 ft. scribed S10 T23S R8W CS BT.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #640, surveyed July 1967/April 1968 (DCSO records Vol. 35 Page(s) 14436-37)

The cor. of secs. 3 and 10 only, perpetuated and recorded by (Cont. Next Page)

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500578

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 10 only (East)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Byron in 1959, monumented with an iron post 1½" dia., firmly set, projecting 12" above ground with brass cap as mkd. in 1959,

from which the original bearing trees:

A W.Fir 33" dia., bears N.32°E., 75 lks. dist. with no marks visible on opened and rotted blaze.

A Fir 60" dia., bears S.53°W., 68 lks. dist. with healed blaze.

A Fir 32" dia., bears N.68°W., 22 lks. dist. with healed blaze.

and bearing trees mkd. by Byron:

A Fir 12" dia., bears N.76°W., 55 lks. dist., with healed double blaze.

A Fir 8" dia., bears S.74°W., 64 lks. dist., with healed double blaze.

Add marks BLM 1967 to brass cap.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2772, surveyed Sept./Nov. 2014 - (DCSO records Vol. 58 Page(s) 23273-4)

The cor. of secs. 3 and 10 only, on the W. bdy. of sec. 11, monumented with an iron post, 1½" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

A W.Fir snag, 36" dia., bears N.32°E., 49.5 ft., with no scribe marks visible on decayed partially healed blaze.

A decayed fir stump, 60" dia., bears S.53°W., 44.9 ft., with a healed blaze.

A fir, 45" dia., bears N.68°W., 15.9 ft., with a healed blaze. (Record and to face, 14.5 ft.)

and a bearing tree mkd. by the Douglas County Surveyor's Office in 1959

A fir, 16" dia., bears S.74°W., 42.2 ft., with a healed blaze at waist height.