

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2567)

Set a post 3 ft. long, 3' sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which
A Fir 40" dia., bears S.39°E., 35 lks. dist. mkd. ¼ S BT
A Dogwood 6" dia., bears N.41°E., 19 lks. dist. mkd. ¼ S BT.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 350 & 538 - surveyed April 1964 - (DCSO records Vol. 32 Page(s) 13540-41)

The ¼ sec. cor. of secs. 23 and 26, determined at record bearing and distance from the original bearing trees:

A down Dogwood 10" dia., bears N.41°E., 19 lks. dist., with no marks visible on open and rotted blaze.

A Fir snag 55" dia., bears S.39°E., 35 lks. dist., with scribe marks ¼ S visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: ¼ $\frac{S\ 23}{S\ 26}$

T 23 S R 8 W
1964

from which new bearing trees

A Fir 15" dia., bears N.38°W., 134 lks. dist. mkd. ¼ S23 BT.

A Fir 31" dia., bears S.77½°E., 78 lks. dist. mkd. ¼ S26 BT.

Fd. OK, Feb. 1981 by L. Roberts - M 86-66

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23404-5)

The ¼ sec. cor. of secs. 23 and 26, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap, oriented S., (properly) mkd.

from which the remains of an original bearing tree

A fir stump, 49" dia., bears S.39°E., 23.1 ft., with illegible scribe marks visible on open blaze.

and the remains of the BTs mkd. by Brooks & Peterson in 1964

A fir stump, 40" dia., bears S.77½°E., 51.5 ft., with a healed blaze.

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A decayed fir stump, 22" dia., bears N.38°W., 87.1 ft., with illegible scribe marks and reverse scribe marks visible from the top of a healed blaze. (Record, 88.4 ft.)
and new bearing trees

A fir, 12" dia., bears S.35°W., 11.0 ft., mkd. ¼ S26 BT.

A fir, 15" dia., bears N.5°W., 18.2 ft., mkd. ¼ S23 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center and has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. angle irons were driven alongside each corner unless an existing guard post was noted in the corner description.

Ron Quimby - Crew: N. Fromdahl & R. Heichel - 4/2019 - C.S.
File 65/102-38

Found - BLM brass cap, properly mkd.
49" Fir stump S.39°E., 23.1 ft, illegible scribe.
40" Fir stump S.77½°E., 51.5 ft, good scar.
22" Decayed Fir stump N.38°W., 87.1 ft, no marks visible.
13" Fir S.35°W., 11.0 ft. visible scribe.
16" Fir N.5°W., 18.2 ft. visible scribe.
New - 8" Fir N.72°E., 5.5 ft. scribed ¼ S23 BT.
9" Fir S.39°E., 19.3 ft. scribed ¼ S26 BT.
Note - Compass decl. 15½°E.