

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 6 Page(s) 2531)

-----  
Set a post cor. secs. 25, 26, 35 and 36, from which  
A Fir 9" dia., bears S.5°E., 11 lks. dist.  
A Fir 10" dia., bears N.62°E., 35 lks. dist.  
A Fir 6" dia., bears N.30°W., 22 lks. dist.  
A Fir 18" dia., bears S.40°W., 61 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2558-59)

-----  
The Sec. cor., which is a post 4" sq., marked T23S S25 on NE.; R8W S36 on SE.; S35 on SW.; and S26 on NW. faces with 1 notch on S. and E. edges, from which  
A Fir 14" dia., bears N.62°E., 35 lks. dist. mkd. T23S R8W S25 BT.  
A Fir 12" dia., bears S.5°E., 11 lks. dist. mkd. T23S R8W S36 BT.  
A Fir 10" dia., bears N.30°W., 22 lks. dist. mkd. T23S R8W S26 BT.  
The SW. bearing tree being gone, I marked  
A Maple 14" dia., bears S.72°W., 64 lks. dist. mkd. T23S R8W S35 BT.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 350 & 538 - surveyed April 1964 - (DCSO records Vol. 32 Page(s) 13536-37)

-----  
The Sec. cor., determined at record bearing and distance from the remaining original bearing trees:  
A down Fir 18" dia., bears S.5°E., 11 lks. dist., with a healed blaze.  
A Maple 25" dia., bears S.72°W., 64 lks. dist. with no marks visible on opened and rotted blaze. (Whipple 1894)  
A sawed Fir stump 25" dia., bears N.30°W., 22 lks. dist. with no marks visible.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 8 W  
S 26 | S 25  
S 35 | S 36  
1964

from which new bearing trees

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A Fir 5" dia., bears N.74°E., 51 lks. mkd. T23S R8W S25 BT  
A Hemlock 8" dia., bears S.75°E., 109 lks. mkd. T23S R8W S36 BT  
A Fir 5" dia., bears S.46°W., 91 lks. mkd. T23S R8W S35 BT  
A Fir 5" dia., bears N.84°W., 87 lks. mkd. T23S R8W S26 BT

Fd. and used in BLM Resurvey by Stephen J. Malloy, Cadastral Surveyor, under Group #1219, Surveyed July/Aug. 1984 - (DCSO records Vol. 47 Page(s) 18092-93)

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch - 9/23/2014 - C.S. File 67/42-3

-----  
Found - A 3¼" dia., brass cap (properly mkd) on a 2" I.D. iron pipe, set plumb and protruding 4" above ground. 1964  
OBT - A fir 6" dia., now a large indistinct root-hole; the center of which bears approx. N.30°W., 14.5 ft. (as per record)  
1893 BT- A maple 14" dia., now a 25" dia., maple with a fully healed, previously opened, blaze (hole in back of tree reveals rotted center, no evidence of face or scribing remains) This tree bears S.72°W., 42.2 ft. (as per record)  
1964 BTs- A fir 5" dia, now a 25" dia., G.Fir with a fully healed single blaze; bears N.74°E., 33.7 ft. (as per record)  
A fir 5" dia., now a small distinct root-hole; bears S.46°W., 60.1 ft. (as per record)  
A fir 5" dia., now a 17" dia., D.Fir with a fully healed single blaze (This blaze faces approx. N.60°E.,, not S.84°E., as record would indicate); bears N.84°W., 57.4 ft. (as per record)  
New - A 13" dia. D.Fir scribed "T23S SR8W CS" "BT" on a double blaze; bears S.45°E., 29.7 ft.  
Fd: A 1/2" iron rod with a yellow forest boundary sign is approx. south 53 ft.  
Note - Monument is on a very gentle NE'ly slope in old mixed Fir reprod with some Maple.  
Compass decl. 15½°E.

David Edwards - Crew: Brant Miller & Eric Sprinkle - 7/11/2017 - C.S. File 65/95-49

-----  
Found - 1964 B.L.M. brass cap in good condition.  
A 25" dia., 2' tall Maple stump ( 1893 B.T. ) bears S.72°W., 42.2'

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

An 18" ( record 25" ) Fir with healed blaze bears  
N.74°E., 33.7' ( 1964 B.T.)  
A 17" dia., 5' tall Fir stump w/healed blaze bears  
N.84°W., 57.4' ( 1964 B.T. )  
The 2014 Fir bearing S.45°E. is now a blowdown.  
The 1/2" dia. iron rod remains as noted in 2014.  
New - Set 6 foot steel posts 2 feet North, South and East  
Note - Immediately West and South of this corner is a  
clearcut.  
Compass decl. 15°E.

---

Fd. OK 4/2019 by R.Quimby C.S. 65/102-37

---

DCSO GPS - 8/2021 - added 12/29/2021 - C.S. File 67/51-27  
Lat: 43°26'50.51" N Long: 123°36'19.09" W

---

Scott Toldness - Crew: Jason Raver & N Peterson - Dec. 19,  
2021 - C.S. File 65/109-38  
-----  
Found - A 3.25" brass cap, on an iron pipe, 0.4' above  
ground, from which:  
A post bears North, 2.0' dist  
A Fir, 26" diam., bears N.71¾°E., 33.66' dist. (rec.  
N.74°E., 33.7), with healed blaze, a tag by "FAB  
4-21-64" and K-TAG BY "LS2339 7/17"

A post bears East, 2.0' dist.  
A post bears Southeast, 0.3' dist.  
A post bears south, 2.0' dist.  
A Fir stump, 19" diam., bears N.84°W., 57.4' dist,  
with healed blaze and tag from 1964  
New - A Fir, 11" diam., bears N.37½°E., 66.4' dist,  
scribed "XBT" with tag by "90216 12/19/21"  
A Fir, 10" diam., bears S.5°E., 169.1' dist, scribed  
"T23SR8WS36BT" with tag by "90216 12/19/21"  
Cleared area of debris. Painted BTs with a 6" band  
at 6' high.  
Added ferrous nails at side center of BTs.  
Compass Declination 14½°E

---

3