

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 6 Page(s) 2531)

Set ¼ sec. post, from which
A Fir 10" dia., bears S.88°E., 27 lks. dist.
A Fir 10" dia., bears S.10°W., 8 lks. dist.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 350 & 538 - surveyed April 1964 - (DCSO records Vol. 32 Page(s) 13537-38)

Point for the ¼ sec. cor., at proportionate distance as based on the original line tree to the S. and the original corner of secs. 23, 24, 25 and 26; there is no remaining evidence of the original corner.

Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd:

¼
S 26 | S 25
T 23 S R 8 W
1964

from which
A Cedar 13" dia., bears S.33°E., 37 lks. dist. mkd. ¼ S25
BT.
A Cedar 10" dia., bears S.28°W., 60 lks. dist. mkd. ¼ S26
BT.

Fd. OK, Nov. 10, 1980 by W.C. Weatherly - C.S. File 58/247

Fd. and used in BLM resurvey by Harvey E. Wofford, Cadastral Surveyor, under Group #1257, Surveyed May/June 1985 - (DCSO records Vol. 48 Page(s) 18238-39)

Ron Quimby - Crew: N. Fromdahl & R. Heichel - 4/2019 - C.S. File 65/102-41

Found - BLM brass cap
28" cedar S.33°E., 24.4 ft., good scar.
21" cedar S.28°W., 39.6 ft., good scar.
New - 15" hemlock S.60°E., 15.7 ft. scribed ¼ S25 BT.
21" hemlock N.63°W., 15.3 ft. scribed ¼ S26 BT.
Note - Compass decl. 15½°E.

Scott Toldness - Crew: Jason Raver, D Vaughan & N Peterson - Dec. 8, 2021 - C.S. File 65/109-41

Found - A 3.25" brass cap, on an iron pipe, flush with the ground, from which
continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir, 18" dia., bears S.57°E., 14.4' dist. (rec. Hemlock S.60°E., 15.7') scribe & tag by "RH 4/19"
A Cedar, 29" dia., bears S.36½°E., 24.4' dist (rec. S.33°E., 24.4') with healed blazes & tag by "FAB"
A Cedar, 21" diam., bears S.27½°W., 39.75' dist. (rec. S.28°W., 39.6'), with healed blazes and tag by "HEW 6/85" & "FAB 4/21/64"
A Fir, 20" diam., bears S.71°W., 15.5' dist. (rec. Hemlock N.63°W., 15.3'), with visible scribing and tag by "JO 4/19"
New - A post bears south, 3.0' dist.
New BT tag on cedar, with updated bearing.
UPDATED BEARING ON BT tag of fir at S.71°W.
Cleared area of debris.
Painted BTs with a 6" band at 6' high.
Added ferrous nails at side center of BTs.
Compass Declination 14½°E.