

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 6 Page(s) 2533)

Set post cor. secs. 1, 2, 11 and 12, from which
An Oak 18" dia., bears S.7°E., 490 lks. dist.
An Oak 15" dia., bears S.0°15'W., 623 lks. dist.
An Ash 18" dia., bears N.88°W., 167 lks. dist.
No tree convenient NE. of cor.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2613)

At the corner to secs. 1, 2, 11 and 12, which is in a grain field, from which corner point,
An Oak 26" dia., bears S.7°E., 490 lks. dist. mkd. T23S R8W S12 BT.
An Oak 20" dia., bears S.0°15'W., 623 lks. dist. mkd. T23S R8W S11 BT.
The NW. bearing tree is gone. I did not think it proper to set post for corner in a cultivated field. Therefore, omitted to do so.

Survey by Arnold G. Gibson, Asst. Engineer - Oregon State Board of Forestry - April 22, 1957 - C.S. File 42/258 and M 5-19

Found - Orig. 18" Oak bears S.7°E., 490 lks., now 40", inside rotted out, old face showing in bark and cast inside.
15" Oak bears S.0°15'W., 623 lks., now missing.
18" Ash bears N.88°W., 167 lks., now missing, point falls in grain field.
Set a 1½" x 36" galv. iron pipe with 3" bronze cap mkd. "OREGON STATE BOARD OF FORESTRY T23S R8W S1 S2 S11 S12 1957 RS 359", 2 ft. under ground, and from which a
21" Oak S.0°15'E., 315.4 ft. scribed T23S R8W S12 BT RS 359.
20" Oak S.52½°W., 330.4 ft. scribed T23S R8W S11 BT. OSBF metal poster on orig. 18" Oak BT, S.7°E.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #640, surveyed July 1967/April 1968 (DCSO records Vol. 35 Page(s) 14433)

The Sec. cor., determined at record bearing and distance from the only remaining original bearing tree
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A W.Oak 38" dia., bears S.7°E., 490 lks. dist., with no marks visible on opened and rotted blaze. and bearing trees mkd. by Gibson in 1957

A W.Oak 25" dia., bears S.0¼°E., 477 lks. dist. with scribe mark T visible on open blaze.

A W.Oak 23" dia., bears S.53°W., 500 lks. dist. with healed blaze.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 76" in the ground, with top 48" below the surface of field, with brass cap mkd:
 T 23 S R 8 W
 S 2 | S 1
 S 11 | S 12
 1967

Les Roberts, LS #1039 - For: International Paper Co. - Oct/Dec. 1982 - C.S. File 58/280 and M 90-29

 CORNER REPORT ONLY
 Found - 1967 BLM brass cap, buried 2.5 ft.
 1957 OSBF brass cap, bears N.2°45'W., 1.08 ft. (buried 2.0 ft.)
 38" Oak snag, S.7°E., 322.5 ft. (no marks) (1860)
 25" Oak S.53°W., 330.2 ft., scar visible. 1957 BT.
 30" Oak, South, 314.4 ft., scar visible. 1957 BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 8/1/2002 - C.S. File 66/34-29

 Found - 1957 OSBF brass cap/iron pipe, 32" below field surface.
 1967 BLM BC/IP not found.
 18" now rotted Oak & roothole position agrees well with rec. S.7°E., 323.4 ft.
 21" now 33" dia., W.Oak with a fully healed single blaze bears S.1½°E., 316.4 ft. (rec. S.0¼°E., 315.4 ft dist. possible face measurement) 1957
 20" now 26" dia., W.Oak with a partially healed rotted blaze illegible scribing visible, bears S.51¼°W., 331.6 ft. (rec. S.52¼°W., 330.4 ft. dist. possible face measurement) 1957 Rescribe with a high single blaze "T23S R8W S11 CS BT"
 19" dia., Maple double blazed & scribed "T23S R8W S11 CS BT" bears S.39½°W., 296.2 ft.
 No trees or bearing objects North of line.
 Compass decl. 17¼°E.