

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 6 Page(s) 2531)

Set ¼ sec. post, from which
A Maple 12" dia., bears S.65°W., 30 lks. dist.
A Fir 15" dia., bears N.80°W., 25 lks. dist.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 350 & 538 - surveyed April 1964 - (DCSO records Vol. 32 Page(s) 13535-36)

The ¼ sec. cor., monumented with an iron pipe 18" long, ½" dia., firmly set 10" in the ground from which the original bearing tree

A down Fir 24" dia., bears N.50°W., 25 lks. dist., with axe marks visible on opened and rotted blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼ $\frac{S\ 25}{S\ 36}$
T 23 S R 8 W
1964

from which new bearing trees

A Cedar 14" dia., bears N.27°W., 93 lks. mkd. ¼ S25 BT.

A Hemlock 8" dia., bears S.14½°E., 38 lks. mkd. ¼ S36 BT.

Reset the iron pipe alongside the iron post.

Survey by Les Roberts - For: International Paper Co. - March 30, 1982 - M 91-74

Found - 1964 BLM brass cap.
14" Hemlock bears S.15°E., 25.7 ft., scar visible.
New BT - 8" Cedar bears N.73½°W., 24.0 ft., scribed.

Fd. and used in Subdivision of sec. 25 by BLM resurvey by Harvey E. Wofford, Cadastral Surveyor, under Group #1257, Surveyed May/June 1985 - (DCSO records Vol. 48 Page(s) 18242)

Scott Toldness - Crew: Jason Raver & N Peterson - Dec. 21, 2021 - C.S. File 65/109-48

Found - A 3.25" brass cap, on an iron pipe, 0.4' above ground, from which:

A post bears east, 2.3' dist.

A hemlock, 26" dia. bears S.14°E., 25.74' dist. (rec. S.15°E., 25.7'), with healed blazes and tag by "AB 64"

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New -

- A dead and down cedar, 22" diam., bears N.74½°W., 24.0' dist. (rec. N.73½°W), fell Northeast
- A Maple, 18" dia., bears S.40°W., 6.0' dist., with healed blazes and tag by "WITTMAYER 8-23-68"
- A post bears north, 2.0' dist.
- A Fir, 12" dia., bears N.81°E., 22.2' dist, scribed "XBT" with LS washer "90216" & tag "90216 12/21/21"
- A post bears west, 2.0' dist.
- A Fir, 21" dia. bears N.20°W, 44.8' scribed "¼S25BT" WITH LS washer "90216" & TAG "90216 12/21/21"

Cleared area of debris.
Painted BTs with a 6" band at 6' high.
Added ferrous nails at side center of BTs.
Compass Declination 14½°E .