

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 722 - Surveyed Aug 1970/Sept. 1970 - (DCSO records Vol. 35 Page(s) 14489)

Point for the center ¼ sec. cor. of sec. 13, at intersection with the E. and W. center line of sec. 13.

Set an iron post 28" long, 2½" dia., 24" in the ground and in a mound of stone, 2 ft. base, to top, with brass cap marked:

C ¼ S 13
1970

from which

A Fir 30" dia., bears S.57°E., 47 lks. dist. mkd. C¼ S13
BT.

A Fir 34" dia., bears N.58½°W., 70 lks. dist. mkd. C ¼ S13
BT.

BLM resurvey by John A. Farmer, Cadastral Surveyor, under Group #1336, Surveyed Aug/Oct. 1986 - (DCSO records Vol. 48 Page(s) 18283)

Point for the center 1/4 sec. cor. of sec. 13, at intersection with the E. and W. center line.

From this point, the center ¼ sec. cor. of sec. 13, erroneously positioned by Jelley, bears N.79°08'E., 0.321 chs. dist., monumented with an iron post, firmly set in a mound of stone, 2 ft. base, to top, with brass cap mkd. and witnessed as described in the official record.

I remove the iron post and at the true corner point
Reset the iron post, 10" in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

C ¼ S 13
1986

from which bearing trees mkd. by Jelley

A Fir 38" dia., bears S.74¼°E., 74 lks. dist. with healed
blaze.

A Fir 39" dia., bears N.36°W., 51 lks. dist. with healed
blaze.