

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T23-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2631)

Marked a Hemlock 24" dia., for sec. corner to secs. 7, 12, 13 and 18, from which

- A Fir 48" dia., bears N.20°E., 42 lks. dist.
- A Fir 48" dia., bears S.30°E., 36 lks. dist.
- A Fir 30" dia., bears S.30°W., 53 lks. dist.
- A Fir 24" dia., bears N.45°W., 2 lks. dist.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #658 - Surveyed Oct/Nov 1967 - (DCSO recs Vol 36 Pg 14603-04)

The Sec. cor. marked with the stump hole of the original corner tree from which the remains of original bearing trees

- A sawed Fir stump 48" dia., bears N.15°E., 42 lks., with fragmentary scribe marks visible on bark blaze. (Rec. N.20°E.)
- A Fir snag 36" dia., bears S.25°E., 25 lks., no marks remaining. (Rec. S.30°E., 36 lks.)
- A sawed Fir stump 36" dia., bears S.33°W., 56 lks., no marks remaining. (Rec. S.30°W., 53 lks.)
- A rotted Fir stump, size indeterminate, bears N.45°W., 2 lks., no marks remaining.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, with brass cap mkd:

T 23 S			
R 10	W R 9	W	
S 12		S 7	
S 13		S 18	
1967			

from which

- A Hemlock 12" dia., bears N.15°E., 53 lks. mkd. T23S R9W S7 BT
- A Hemlock 14" dia., bears S.9°E., 28 lks. mkd. T23S R9W S18 BT.
- A Hemlock 11" dia., bears S.42°W., 41½ lks mkd T23S R10W S13 BT
- A Hemlock 15" dia., bears N.11°W., 45 lks. mkd T23S R10W S12 BT

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23214)

The cor. of secs. 7, 12, 13, & 18; monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd.
 from which the remains of the original bearing trees

continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T23-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, 48" dia., bears N.15°E., 27.7 ft., no marks visible.
A fir stump, 36" dia., bears S.33°W., 37.0 ft., no marks visible.
and the bearing trees mkd. by Beck in 1967
A hemlock, 23" dia., bears N.15°E., 35.0 ft., with a healed blaze.
A hemlock, 23" dia., bears S.9°E., 18.5 ft., with a healed blaze.
A hemlock, 14" dia., bears S.42°W., 27.4 ft., with a healed blaze.
A hemlock, 17" dia., bears N.11°W., 29.7 ft., with a healed blaze.
From the corner
N.1°33'40"W., 135 ft dirt road, 10 ft wide, bears East & West
Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.
Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.
An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.
NAD 1983 (2011)
Latitude: 43°34'23.30"N. Longitude: 123°49'03.01"W.