

PRIMARY CORNER DESCRIPTION 1/4 Secs. 7 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2637)

Set a Fir post 5 ft. long 5" dia., 20" in ground for the ¼ sec. corner between Secs. 7 & 18, from which
A Fir, 40" dia., bears N.20°E., 20 lks.
A Fir, 30" dia., bears S.25°W., 32 lks.

BLM Dependent resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group #703 surveyed July 1969 - May 1970 - (DCSO records Vol. 35 Page(s) 14565)

Point for ¼ sec. cor. of secs. 7 & 18, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
T23S R9W
¼ S 7
 S 18
 1969

from which
A Hemlock, 11" dia., bears N.51°W., 28½ lks. mkd: ¼ S7 BT.
A Hemlock, 15" dia., bears S.15°E., 37 lks. mkd: ¼ S18 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2074, surveyed April/June 2004 - (DCSO records Vol. 54 Page(s) 21263)

The ¼ sec. cor. of secs. 7 & 18, monumented with an iron post, 2" dia., firmly set, projecting" above ground, with brass cap (properly) mkd.
from which the bearing trees mkd. by Jelley and Steward
A hemlock, 25" dia., bears S.15°E., 22.7 ft., with a healed blaze. (Record, 24.4 ft.)
A hemlock, 18" dia., bears N.51°W., 18.8 ft., with no scribe marks visible on partially healed blaze.