

PRIMARY CORNER DESCRIPTION Cor. Secs. 29 & 32 only (West line)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2633)

-----  
Marked a Fir, 24" dia., for the cor. to secs. 29, 30, 31 & 32, from which

- A Fir, 10" dia., bears N.10°E., 34 lks.
- A Fir, 14" dia., bears S.10°E., 26 lks.
- A Fir, 30" dia., bears S.45°W., 19 lks.
- A Fir, 30" dia., bears N.5°W., 43 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2654)

-----  
Intersect N & S line 240 lks., N of cor. os secs. 29, 30, 31, & 32, which is

A Fir, 24" dia., marked & witnessed as described by the surveyor general.

I set, at the point of intersection, a sandstone, 12" by 9 by 5" in the ground for closing cor. of secs. 29 & 32, marked C C on E; with 1 groove on S & 5 grooves on e faces; from which,

- A Maple, 4" dia., bears N.37°E., 22 lks., mkd: T23S R9W S29 BT.
- A Dogwood, 3" dia., bears S.23°E., 48 lks., mkd: T23S R9W S32 BT.

I destroyed all marks on old corner & BTs referring to these secs.

Michael S. McDowell - For: Weyerhaeuser Co. - Feb. 21, 1977 - M63-23 & C.S. File 58/139

-----  
Set - 1½" gal. I.P. with brass cap, from which  
4" Fir BT scribed bears N.4°E., 33.0 ft  
42" Fir BT bears S.16°E., 92.5 ft.

**NOTE:** This corner set in error, see letter dated 4/12/1978 in C.S. File 58/139

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16223)

-----  
Point for the closing cor. of secs. 29 & 32, at proportionate distance; there is no remaining evidence of this orig. cor.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked: continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200202

PRIMARY CORNER DESCRIPTION Cor. Secs. 29 & 32 only (West line)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>T23S R9W  S 30   S 29 CC          S 32  1977</p>
<p>from which  A Maple, 6" dia., bears N.24½°E., 80½ lks., mkd: T23S R9W  S29 CC BT.  A Fir, 4" dia., bears S.77 3/4°E., 55 lks., mkd: X BT.  Set a 5 ft. steel fence post alongside iron post.</p>
<p>Henry R. Reppeto - For: Weyerhaeuser Co. - April 12, 1978 -  C.S. File 58/139  -----</p> <p>Partial content of letter dated April 12, 1978 to Douglas Co. Surveyor from Weyerhaeuser:  "We have destroyed all accessories to the corners we set (NE Cor. Sec. 31 and the NW Cor.  Sec. 32) as well the East 1/4 Cor. of Sec. 31. Enclosed is a plat for the corrected position of  the East ¼ corner of sec. 31, based on the cadastral location of the NE corner and latest GLO  record distances &amp; bearings". See M 63-23 for orig. Weyerhaeuser map &amp; C.S. 58/139 for  replacement.</p>