

PRIMARY CORNER DESCRIPTION Cor. Secs. 7 & 18 East line

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2636-7)  
-----  
Set a Chinquapin post, 5 ft. long, 5" dia., 20" in the ground for the corner to secs. 7, 8, 17, & 18, from which,  
A Fir, 60" dia., bears N.10°E., 62 lks.  
A Fir, 20" dia., bears S.60°E., 42 lks.  
A Fir, 50" dia., bears S.45°W., 27 lks.  
A Fir, 40" dia., bears N.60°W., 15 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2655)  
-----  
NE cor. of secs. 18, which being gone, I set a Hemlock post, 3 ft. long, 4" sq. 24 ft. in the ground for cor. of secs. 7, 8, 17, & 18 marked & witnessed as described by the surveyor general.

BLM Dependent resurvey by James E. Jelley and Rolla R. Steward, Cadastral Surveyors under Group #703 surveyed July 1969 - May 1970 - (DCSO records Vol. 35 Page(s) 14564)  
-----  
the cor. of secs. of 7 & 18, on the W. bdy. of sec. 17, monumented with a wooden stake, 3" sq., firmly set, projecting 18" above ground from which the OBTs:  
A sawed Fir stump, 65" dia., bears N.10°E., 72 lks., no marks visible on bark blaze. (Rec. 62 lks)  
A sawed Fir stump, 32" dia., bears S.60°E., 42 lks., no marks visible on open blaze.  
A sawed Fir stump, 50" dia., bears S.45°W., 27 lks., no marks visible on bark blaze.  
A sawed Fir stump, 36" dia., bears N.60°W., 15 lks., no marks visible on bark blaze.  
and a tree of which I have no record  
A Fir, 12" dia. bears S.26°E. 13 lks. mkd: T23S R9W S17 BT  
At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:  
T23S R9W  
S 7 S 17  
S 18  
1969  
from which new BTs  
A Fir, 10" dia., bears S.45½°W., 25 lks., mkd: T23S R9W S18 BT.  
A Fir, 8" dia., bears N.55°W., 12 lks. mkd: T23S R9W S7 BT