

PRIMARY CORNER DESCRIPTION North Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2638)

Set a Cedar post 5 ft. long, 5" in dia., 20" in ground for the corner to secs. 20, 21, 28 & 29, from which,
A Hemlock, 12" dia., bears N.45°E., 5 lks.
A Fir, 8" dia., bears S.35°E., 23 lks.
A Fir, 8" dia., bears S.18°W., 29 lks.
A Fir, 16" dia., bears N.25°W., 11 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2647-8)

Intersect S. bdy of sec. 20, 321 lks. E of ¼ sec. cor. bet. secs. 20 & 29.
Set a sandstone, 12x12x10 ins., 8" in the ground for cor. of secs. 28 & 29, mkd. with CC on S and 2 grooves on S and 4 grooves on E faces; from which,
A Vine-Maple, 4" dia., bears S.49°W., 62 lks., mkd: T23S R9W S29 BT.
An Alder, 5" dia., bears S.60°E., 41 lks., mkd: T23S R9W S28 BT.
This corner stands 300 ft. below ¼ sec. cor.

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16216)

Point for the closing cor. of secs. 28 & 29, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T23S R9W
S 20

S 29 | S 28
C C
1977

from which
A Fir, 5" dia., bears S.11½°E., 106 lks., mkd: X BT.
A Fir, 8" dia., bears S.24¼°W., 89 lks., mkd: T23S R9W S29 CC BT.