TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 20 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2638)

Set yew post 50" long 5" in dia., 20" in ground for the ¼ sec. corner between secs. 20 & 21, from which
A Cherry, 6" dia., bears East 20 lks.
A Cherry, 60" dia., bears S.5°W., 43 lks.

A. R. Evans - Nov. 1951 - C.S. File 41/25 & 41/6-2

Set - 1" Iron pipe for corner.
Found - 60" Fir which bears S.5°W., 43 lks. Government notes call for 60" Cherry. Found bark blaze which faces properly, BT scribe very old.

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16212)

Point for the ¼ sec. cor. of sec. 20 only, at midpoint latitudinally on the E. bdy of sec. 20; there is no remaining evidence of the orig. corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T23S
R9W
¼ S20
1977

from which
A Hemlock, 20" dia. bears S.52½°W., 75½ lks. mkd: ¼ S20 BT
A Hemlock, 13" dia., bears N.71½°W., 38½ lks., mkd: X BT.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23308-9)

The ¼ sec. cor. of sec. 20 only, on the W. bdy. of sec. 21, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd. from which the remains of the BTs mkd. by Bowder in 1977
A root hole bears S.52½°W., 49.8 ft., alongside of which is a down decayed hemlock, size indeterminate, no marks visible.
A hemlock, 27" dia., bears N.71½°W., 25.4 ft., with a healed blaze.
and a new bearing tree
A hemlock, 10" dia., bears S.54½°W., 34.3 ft mkd. ¼ S20 BT
Drive an aluminum angle iron alongside the cor.