

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 21 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2638)

Set yew post 50" long 5" in dia., 20" in ground for the ¼ sec. corner between secs. 20 & 21, from which
A Cherry, 6" dia., bears East 20 lks.
A Cherry, 60" dia., bears S.5°W., 43 lks.

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16212)

Point for the ¼ sec. cor. of sec. 21 only, at midpoint latitudinally on the W. bdy of sec. 20; there is no remaining evidence of the orig. corner.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T23S
R9W
¼ S21
1977

from which

A W.Fir, 27" dia., bears N.50°E., 110 lks., mkd: ¼ S21 BT.
A Fir, 9" dia., bears S.69 3/4°E., 18 lks., mkd: ¼ S21 BT.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23309)

The ¼ sec. cor. of sec. 21 only, on the E. bdy. of sec. 20, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd. from which the remains of the BTs mkd. by Bowder in 1977

A hemlock, 33" dia., bears N.50°E., 72.6 ft., with a healed blaze. (Record, white fir.)

A decayed fir snag, 11" dia., bears S.69¾°E., 11.9 ft., with a healed blaze.

and a new bearing tree

A fir, 26" dia., bears S.7¾°E., 31.4 ft., mkd. ¼ S21 BT.
Drive an aluminum angle iron alongside the cor.