



PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A bridge spike driven in the top of a 38" Fir stump, directly above its root collar bears N.29°W., 72.6 ft.

We place a steel fencepost with survey marker sign attached approx. one foot east of the corner.

Note - This corner lies in a clear cut unit in dense brush and logging debris on a NW facing slope & approx. 100 ft. south east of a small stream. Compass declination setting: 20° east.

Fd. & used on BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16220)

Tony Hostetter - For: Weyerhaeuser Co. - Dec. 2011 - C.S. File 65/76-9

-----

Found - 1975 Douglas Co. Surveyor Brass cap.  
30" Fir snag, orig. BT, bears N.15°E., 31.0 ft. to center.  
48" Fir stump, Prahar BT, WEYCO tag, bears N.52°E., 23.8 ft. to center.

New BTs- 22" Fir, scribed "S28 ¼ BT" WEYCO tag, bears N.1°44'E., 24.7 ft. to spike in root collar.  
14" Fir, scribed "S28 ¼ BT" WEYCO tag, bears N.45°05'E., 20.6 ft. to spike in root collar.  
11" Fir, scribed "S33 ¼ BT" WEYCO tag, bears S.34°33'E., 19.9 ft. to spike in root collar.  
10" Fir, scribed "S28 ¼ BT" WEYCO tag, bears N.78°07'W., 8.9 ft. to spike in root collar.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23307)

-----

The ¼ sec. cor. of secs. 28 & 33, perpetuated by Hostetter, in 2011, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree

A decayed fir snag, 26" dia., bears N.15°E., 31.0 ft., with no marks visible on open blaze.

and the remains of the BTs mkd. by the Douglas County Surveyor's Office in 1975 (Record, Prahar)

A decayed fir stump, 48" dia., bears N.52°E., 23.8 ft., no marks visible.

A decayed fir stump, 38" dia., bears N.31°W., 72.6 ft., no marks visible. (Record, N.29°W.)

continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the bearing trees mkd. by Hostetter

- A fir, 24" dia., bears N.1½°E., 26.1 ft., with pitchy partially healed blaze and a nail at the base on the front center.
- A fir, 16" dia., bears N.44¾°E., 21.0 ft., with pitchy partially healed blaze and a nail at the base on the front center.
- A fir, 12" dia., bears S.34¾°E., 20.3 ft., with pitchy partially healed blaze and a nail at the base on the front center.
- A fir, 11" dia., bears N.78°W., 9.7 ft., with illegible scribe marks visible on pitchy partially healed blaze and a nail at the base on the front center.

Alongside the cor. is an iron rod, 3/4" dia., firmly set, projecting 18" above ground, and a steel fence post with a Douglas County Survey Marker sign.