

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2682)

-----  
A point, 80 ft. below top of spur, set a maple post, 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd: 21 on N face & 28 on S face from which  
A Fir, 28" dia., bears S.30°W., 18 lks., mkd: ¼ S28 BT.  
A Fir, 24" dia., bears N.36°W., 13 lks., mkd: ¼ S21 BT.

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16215)

-----  
The ¼ sec. cor. of secs. 21 & 28 determined at the record bearing & distance from each of the orig. BTs:  
A decayed Fir stump, size indeterminate, bears N.36°W., 13 lks., no marks visible.  
A decayed Fir stump, 45" dia., bears S.30°W., 18 lks., with scribe marks BT visible on bark blaze.  
At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:  
T23S R9W  
¼  $\frac{S\ 21}{S\ 28}$   
1977  
from which new BTs  
A Fir, 5" dia., bears N.76½°E., 6½ lks., mkd: ¼ S21 BT.  
A Fir, 4" dia., bears S.9 3/4°W., 22 lks., mkd: X BT.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23308)

-----  
The ¼ sec. cor. of secs. 21 & 28, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd.  
from which the remains of the original bearing trees  
A decayed fir stump, 42" dia., bears S.30°W., 11.9 ft., with no marks visible on partially healed blaze.  
A decayed fir stump, size indeterminate, bears N.36°W., 8.6 ft., no marks visible.  
and new bearing trees  
A hemlock, 10" dia., bears S.20°E., 15.4 ft. mkd. ¼ S28 BT  
A fir, 11" dia., bears N.48½°W., 23.1 ft., mkd. 1/4 S21 BT  
Drive an aluminum angle iron alongside the cor.