

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2660)

Set a Maple post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S9 on N face & 16 on S face, from which:
A Fir, 50" dia., bears N.17°E., 59 lks., mkd: ¼ S9 BT.
A Fir, 60" dia., bears S.66°W., 30 lks., mkd: ¼ S16 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - V. Perron - June 1970 - C.S. File 54/60-50

Found - 1" I. Pipe at corner, unrecorded, set from orig. BT stumps.
Orig. 50" Fir, now 60" stump, N.17°E., 38.9 ft., no bark or scribe found.
Orig. 60" Fir, now 64" stump, S.66°W., 19.8 ft., old bark blaze, no scribe, blaze in poor condition.
Creek call to W. fits this location.
DID NOT SET BRASS CAP, as pipe is in good condition.
New BTs- 5" D.Fir N.32°W., 16.4 ft., mkd: ¼ S9 CS BT.
6" Alder S.26°E., 6.4 ft., mkd: ¼ S16 CS BT