

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23223-4)

Point for the center ¼ sec. cor. of sec. 4.
Set a stainless steel post, 28" long, 2½" dia., 27" in the ground, with brass cap mkd.

T 23 S R 9 W
C ¼ S 4
2014

from which

A fir, 20" dia., bears S.86½°E., 11.7 ft., mkd. C¼ S4 BT.

A hemlock, 28" dia., bears S.69½°W., 19.2 ft., mkd. C¼ S4 BT.

From this cor., a point established as the center ¼ sec. cor. of sec. 4 during an unofficial administrative survey by the FHWA, in 1974, bears S.19°16'41"W., 13.20 ft. This position was established without proper authority and is not utilized in this survey; monumented with a steel fence post, firmly set, projecting 2½ ft. above ground, from which the remains of the bearing trees mkd. by FHWA

A decayed fir stump, size indeterminate, bears S.81½°E., 31.3 ft., no marks visible.

A decayed hemlock high stump, size indeterminate, bears N.26¼°W., 53.7 ft., with remains of a healed blaze.

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.